



# HILLTOWN TOWNSHIP

13 West Creamery Road

P.O. Box 260

Hilltown, PA 18927

(215) 453-6000

July 6, 2005

To the residents of Longleaf II,

This is the fifth letter in a series of updates to the concerns voiced at the May 23, 2005 meeting of the Hilltown Township Board of Supervisors. As a reminder, the concerns raised were related to the fire sprinkler systems in the second phase of the Longleaf development.

We apologize for the difficulties and delays in releasing these updates. We assure you that we are diligently working on keeping you abreast of the progress being made in this study.

According to Mr. Larry Wargo: "The Qualified pipe sample taken last week passed compression testing. The fluid samples taken at the same time are not yet complete. All HAS testing is still underway." – Via email 7/5/05

The Township has begun the inspection process. We are calling each person who has left us a phone number to contact. We will then be sending out individual emails to those who have not. This will be a process that will take some time. Please be patient as we work our way through the list.

If your system has been shut off, there will be no problems in conducting this inspection. The inspection is being used to gather data and review the sprinkler riser for code compliance.

If you have not provided us with a phone number or email address and are interested in participating in this voluntary inspection, please send an email with your name, address, and phone number to [djenkins@hilltown.org](mailto:djenkins@hilltown.org) and we will add you to the list. Although this entire process will be optional on your part, we strongly recommend that you agree, as it will allow for more complete and accurate data to evaluate.

Should you have any further questions, please do not hesitate to contact the Township so that we may include it in a future update.

Again, we encourage you to send an email to [djenkins@hilltown.org](mailto:djenkins@hilltown.org) to receive these updates by email. Please be sure to identify your street address, so that we may reduce the duplicate mailings.

Respectfully,

Daniel A. Jenkins, MCP  
Fire Marshal

David W. Taylor, CBO  
Building Code Official